

SSA-223771: SISCO Stack Vulnerability in SIPROTEC 5 Devices

Publication Date: 2022-12-13
Last Update: 2023-03-14
Current Version: V1.2
CVSS v3.1 Base Score: 7.5

SUMMARY

A vulnerability in the third party component SISCO MMS-EASE could allow attackers to cause a denial of service condition with SIPROTEC 5 devices.

Siemens has released updates for several affected products and recommends to update to the latest versions. Siemens is preparing further updates and recommends specific countermeasures for products where updates are not, or not yet available.

AFFECTED PRODUCTS AND SOLUTION

Affected Product and Versions	Remediation
SIPROTEC 5 6MD85 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757428/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 6MD85 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757428/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 6MD86 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757428/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 6MD86 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757428/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 6MD89 (CP300): All versions < V7.80	Update to V7.80 or later version https://support.industry.siemens.com/cs/ww/en/view/109742950/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7KE85 (CP200): All versions < V7.80	Update to V7.80 or later version https://support.industry.siemens.com/cs/ww/en/view/109757430/ See further recommendations from section Workarounds and Mitigations

SIPROTEC 5 7KE85 (CP300): All versions < V7.80	Update to V7.80 or later version https://support.industry.siemens.com/cs/ww/en/view/109757430/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SA82 (CP100): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SA84 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SA86 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SA86 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SA87 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SA87 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SD82 (CP100): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SD84 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SD86 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations

SIPROTEC 5 7SD86 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SD87 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SD87 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SJ81 (CP100): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109751934/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SJ82 (CP100): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109751934/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SJ85 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109751934/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SJ85 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109751934/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SJ86 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SJ86 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SK82 (CP100): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757434/ See further recommendations from section Workarounds and Mitigations

SIPROTEC 5 7SK85 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757434/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SK85 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757434/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SL82 (CP100): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SL86 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SL86 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SL87 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SL87 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SS85 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757429/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7SS85 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757429/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7ST85 (CP200): All versions	Currently no fix is available See recommendations from section Workarounds and Mitigations

SIPROTEC 5 7UM85 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757431/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7UT82 (CP100): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757438/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7UT85 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757438/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7UT85 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757438/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7UT86 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757438/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7UT86 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757438/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7UT87 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757438/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7UT87 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757438/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7VE85 (CP300): All versions < V7.80	Update to V7.80 or later version https://support.industry.siemens.com/cs/ww/en/view/109749865/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 7VK87 (CP200): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations

SIPROTEC 5 7VK87 (CP300): All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109757433/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 Communication Module ETH-BA-2EL: All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109740816/ See further recommendations from section Workarounds and Mitigations
SIPROTEC 5 Communication Module ETH-BB-2FO: All versions < V7.58	Update to V7.58 or later version https://support.industry.siemens.com/cs/ww/en/view/109740816/ See further recommendations from section Workarounds and Mitigations

WORKAROUNDS AND MITIGATIONS

Siemens has identified the following specific workarounds and mitigations that customers can apply to reduce the risk:

- Disable IEC 61850 communications on the affected port of the device
- Restrict access to port 102/tcp to trusted IP addresses only

Product-specific remediations or mitigations can be found in the section [Affected Products and Solution](#). Please follow the [General Security Recommendations](#).

GENERAL SECURITY RECOMMENDATIONS

Operators of critical power systems (e.g. TSOs or DSOs) worldwide are usually required by regulations to build resilience into the power grids by applying multi-level redundant secondary protection schemes. It is therefore recommended that the operators check whether appropriate resilient protection measures are in place. The risk of cyber incidents impacting the grid's reliability can thus be minimized by virtue of the grid design. Siemens strongly recommends applying the provided security updates using the corresponding tooling and documented procedures made available with the product. If supported by the product, an automated means to apply the security updates across multiple product instances may be used. Siemens strongly recommends prior validation of any security update before being applied, and supervision by trained staff of the update process in the target environment. As a general security measure Siemens strongly recommends to protect network access with appropriate mechanisms (e.g. firewalls, segmentation, VPN). It is advised to configure the environment according to our operational guidelines in order to run the devices in a protected IT environment.

Recommended security guidelines can be found at: <https://www.siemens.com/gridsecurity>

PRODUCT DESCRIPTION

SIPROTEC 5 devices provide a range of integrated protection, control, measurement, and automation functions for electrical substations and other fields of application.

VULNERABILITY CLASSIFICATION

The vulnerability classification has been performed by using the CVSS scoring system in version 3.1 (CVSS v3.1) (<https://www.first.org/cvss/>). The CVSS environmental score is specific to the customer's environment and will impact the overall CVSS score. The environmental score should therefore be individually defined by the customer to accomplish final scoring.

An additional classification has been performed using the CWE classification, a community-developed list of common software security weaknesses. This serves as a common language and as a baseline for weakness identification, mitigation, and prevention efforts. A detailed list of CWE classes can be found at: <https://cwe.mitre.org/>.

Vulnerability CVE-2015-6574

The SNAP Lite component in certain SISCO MMS-EASE and AX-S4 ICCP products allows remote attackers to cause a denial of service (CPU consumption) via a crafted packet.

CVSS v3.1 Base Score	7.5
CVSS Vector	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H/E:P/RL:O/RC:C
CWE	CWE-770: Allocation of Resources Without Limits or Throttling

ACKNOWLEDGMENTS

Siemens thanks the following party for its efforts:

- Vera Mens from Claroty for reporting the vulnerability

ADDITIONAL INFORMATION

For further inquiries on security vulnerabilities in Siemens products and solutions, please contact the Siemens ProductCERT:

<https://www.siemens.com/cert/advisories>

HISTORY DATA

V1.0 (2022-12-13):	Publication Date
V1.1 (2022-12-21):	Corrected affected products list, fix versions, and download links
V1.2 (2023-03-14):	Corrected affected products list, fix versions, and download links

TERMS OF USE

Siemens Security Advisories are subject to the terms and conditions contained in Siemens' underlying license terms or other applicable agreements previously agreed to with Siemens (hereinafter "License Terms"). To the extent applicable to information, software or documentation made available in or through a Siemens Security Advisory, the Terms of Use of Siemens' Global Website (https://www.siemens.com/terms_of_use, hereinafter "Terms of Use"), in particular Sections 8-10 of the Terms of Use, shall apply additionally. In case of conflicts, the License Terms shall prevail over the Terms of Use.